

Project No.	Client	Location	Boring No.	Monitoring Well No.	Date
01105	Metro Car Wash	2950 Harbor, CM	CB-2	N/A	August 8, 2005
PID	BLOWS/ft. Sampler	DEPTH in feet	USCS Designation & Soil Type	Color	Secondary Characteristics
0	6-13-21	5	CL-Silty Clay	Brown	Stiff, SI Damp, No Odor
0	4-4-6	10	SM-Silty Sand	Tan to Brown	Loose, Dry
0	7-13-16	15	CL-Silty Clay	Grey to Brown	Stiff, Dry, No Odor
0	8-18-24	20		Grey	
0	10-17-22	25		Light Grey to Grey	
0	7-9-15	30			
0	9-12-23	35	SM-Silty Sand	Light Grey	M. Dense
0	7-14-22	40	CL-Silty Clay	Greyish Brown	Stiff, Damp
0	21-39-50/3"	45	SM-Silty Sand	Tan	Very Dense, Moist
0	15-18-23	50			
0	28-50/5"	55			
0	33-50/4"	60		Tan to Grey	
0	35-50/5"	65		Grey	
0	31-50/5"	70			Wet
0	27-50/5"	75	SP-Poorly Graded Sands	Brown	
Field Engineer	Drilling Contractor	Drilling Foreman	Boring terminated at 75 feet below grade. Groundwater at 67'. Boring backfilled with soil of origin and capped with bentonite plug (2'). Resurfaced with concrete		
M. Anselmo	J & H	Conrad			